

STATION LOG.

Date	Called	G.M.T.	Called by	CW Phone	QRG	His			WX	My			Remarks or Message
						T	QSA	R		T	QSA	R	
✓ 31-7-35	G5DY	2230	—	CW	1860	9	5	7/8	Clear Sky, end day	5	6	6	Left office
1-8-35	G5DY	2130	—	CW	1860	.	.	.	Ant. Dry	.	.	.	N.D.
1-8-35	G6G0	2305	.	CW	1860	.	.	.	"	.	.	.	N.D.
✓ 3-8-35	G5B3	1000	G5DY	CW	1860	9	5	7	"	9	5	5	Send Rice note on 10/8 mod. P.W.
3-8-35	G5BY	1000	.	F	1860	.	5	4	"	5	9	9	9 same note on 10/8
3-8-35	Test	2240	.	CW	1860	.	.	.	overcast	.	.	.	N.D.
✓ 4-8-35	G5OD	2255	.	CW	1860	9	4	5	Cloudy	9	5	6	N.D.
4-8-35	G6KD	0910	.	F	1860	9	4	5	Cloudy	9	5	6	March special
4-8-35	G5MS	0950	G5B3	CW	1860	.	.	.	Cloudy	.	.	.	N.D.
4-8-35	G5OD	0955	.	F	1860	.	2	4	Cloudy	.	5	6	General fine 9 mins 5/15
4-8-35	G6AU	1140	.	F	1860	.	5	6	Cloudy	.	5	7	"
4-8-35	G5ZJ	1900	.	CW	1860	.	5	4	Cloudy	.	5	6	N.D.
4-8-35	G6CS	2255	.	CW	1300	9	4+	7 1/2	Cloudy	9	5	5	N.D.
5-8-35	G6CS	0925	.	F	1860	.	5	5	Agony/Blowing	.	5	5	his report on good signal.
5-8-35	TEST	0855	.	F	1860	.	.	.	Ants	.	.	.	N.D.
5-8-35	GAKD	0945	.	CW	1860	9	5	8	Ants	.	.	.	N.D.
5-8-35	TEST	1010	.	CW	1860	.	.	.	Ants	.	.	.	N.D.
5-8-35	TEST	1145	.	CW	7095	9	5	7	Cloudy	9	5	5 1/2	not work. his summary R2
5-8-35	G2DF	1210	.	CW	7095	9	5	7	Ants	9	5	8	Ants etc
5-8-35	G6MU	2235	.	CW	7095	9	4	3/4	Clear	9	5	8	got R6 part working on.
5-8-35	G5OD	2250	.	CW	1860	9	5	5	Clear	9	4	6	Ants
5-8-35	G2ND	0915	.	CW	7095	7	4	5	Ants	8	5	7	from 708 he faded out - Ants